## **Technical Bulletin**

**N°: TECB-**08-12-15\_RO

**Date**: 09/12/2015

Diamond model considered: FSM-16E/N

Diamond catering equipment

Your professional partner

Problem: Leakage risk

Technical solution suggested : Add a silicon gasket

Action (what-when): Since October 2015 we have add a silicon gasket around the capillary clamp press

Defective spare parts codes: nothing

New replacing spare parts codes: added of high temperature silicone



